

101708448

C.R.L.



GEN-0350 / 133546

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number: 7,026,894 B2

Issued: April 11, 2006

Name of Patentee: Michael Tobin, et al.

Title of Invention: METHOD AND APPARATUS FOR MAGNETICALLY TRIPPING CIRCUIT BREAKERS

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR APPLICANTS' MISTAKE (37 C.F.R. 1.323)**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction  
Branch of the Patent Issue Division

Sirs:

It is noted that errors appear in this patent of a typographical nature or character, as more fully described below. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being

03/21/2006 MGEDR001 00000079 061130 7026894  
01 FC:1011 100.00 DA

*Certificate  
of Correction  
AUG 23 2006*

I certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on
August 15, 2006
(Date of Deposit)
Rosemarie Barbara
(Name of Person Mailing Paper)
<i>Rosemarie Barbara 8-15-06</i>
Signature Date

AUG 24 2006

suitable for printing.

The errors are in the body of the patent in: In the Figures, Figure 2; column 5, line 28; column 6, line 11; and column 7, line 67.


Please send the Certificate of Correction to:

Cantor Colburn LLP  
55 Griffin Road South  
Bloomfield, Connecticut 06002

Please charge the amount of \$100.00, as required by 37 C.F.R. 1.20(a) or any additional charges with respect to this request or otherwise, to Deposit Account No. 06-1130 maintained by Patentees' attorneys.

Respectfully submitted,

CANTOR COLBURN LLP

By: 

David A. Fox  
Registration No. 38,807  
55 Griffin Road South  
Bloomfield, Connecticut 06002  
Telephone: (860) 286-2929  
Customer No. 23413

Date: August 15, 2006

8/15/2006

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : 7,026,894 B2

Page \_\_ 1\_\_ of \_\_ 1\_\_

DATED : April 11, 2006

INVENTOR(S) : Michael Tobin, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Figures,

Figure 2, below reference Numeral "124", delete "285" and insert therefor -286--.

Column 5,

Line 28, after "drive pin", delete "285" and insert therefor -286--.

Column 6,

Line 11, before "to", delete "285" and insert therefor -286--.

Column 7,

Line 67, after "referenced" delete "item" and insert therefor -items--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,026,894 B2

Cantor Colburn LLP  
55 Griffin Road South  
Bloomfield, CT 06002

No. of additional copies

0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing this form, call 1-800-PTO-9199 and select option 2.*

AUG 24 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE**  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,026,894 B2

Page 1 of 1

DATED : April 11, 2006

INVENTOR(S) : Michael Tobin, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Figures.

Figure 2, below reference Numeral "124", delete "285" and insert therefor -286--.

Column 5.

Line 28, after "drive pin", delete "285" and insert therefor -286--.

Column 6.

Line 11, before "to", delete "285" and insert therefor -286--.

Column 7.

Line 67, after "referenced" delete "item" and insert therefor -items--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,026,894 B2

Cantor Colburn LLP  
 55 Griffin Road South  
 Bloomfield, CT 06002

No. of additional copies

0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing this form, call 1-800-PTO-9199 and select option 2.*

*Patent Office*